



Cinghie per squadratori uscita forno

Square process kiln exit



TIPO 1, 3:

L=	MM
A=	MM
B=	MM
S=	MM
C=	MM
T=	MM

TIPO 2, 4:

A=	MM
S=	MM
C=	MM
T=	MM



CINGHIA T10 LARGA 25
BELT T10 WIDTH 25

14630	3080	5750	5800
14000	2970	4080	6950
13300	2750	3950	6600
12850	2720	3675	6455
12500	2530	5020	4950
12200	2500	4750	4950
12000	2430	3620	5950
11200	2250	3400	5550
11150	2250	4450	4450
10700	2120	4190	4390
17200	2430	7460	7310
A	B	C	D

CINGHIA T10 LARGA 16
BELT T10 WIDTH 16

11000	2340	3330	5330
10900	2250	4325	4325
10900	2250	3100	5550
10700	2300	3100	5300
10700	2120	4190	4390
10670	2380	3205	5085
10630	2130	3200	5300
10350	2280	3105	4985
10350	2100	3100	5150
10180	2100	3055	5025
10170	2130	3080	4960
9880	2100	2950	4830
9810	1975	4935	2900
9650	2130	2820	4700
9565	2100	2905	4560
9450	1975	4475	3000
9440	1810	2910	4720
9080	1850	2790	4440
9000	1700	2800	4500
8850	2420	4230	2200
8450	1750	2500	4200
8400	2000	4000	2400
8300	2100	4100	2100
8140	1650	2530	3960
8040	1540	4000	2500
7980	1580	2260	4140
7900	1580	2970	3350
7770	1875	3710	2185
7100	1300	2250	3550
7410	2000	3530	1880
7160	1875	3405	1880
7000	1350	2100	3550
6910	1750	3280	1880
A	B	C	D

CINGHIA T10 LARGA 16
BELT T10 WIDTH 16

14000	2970	4080	6950
13750	2970	6890	3890
13450	2970	6740	3740
13100	2750	3850	6500
12850	2720	3675	6455
12750	2730	6385	3635
12680	2600	3750	6330
12450	2730	6235	3485
12200	2530	3610	6060
11950	2500	3445	6005
11950	2520	3465	5965
11940	2600	3250	6090
11900	2430	3570	5900
11700	2500	3350	5850
11650	2430	3390	5830
11500	2400	3300	5800
11450	2430	3290	5730
11300	2400	3300	5600
11300	2300	3500	5500
11150	2280	3435	5435
11100	2130	3400	5570
A	B	C	D

